

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Hyun Sook KIM et al.

Application No.: 10/811,852

Confirmation No.: 2332

Filed: March 30, 2004

U.S. Patent No.: 7,444,842

Issued: November 4, 2008

For: DRUM WASHING MACHINE AND METHOD OF CONTROLLING THE SAME



ATTENTION

CERTIFICATE OF CORRECTION
Certificate

BRANCH

DEC 18 2008

of Correction

Commissioner for Patents
PO Box 1450
Alexandria, VA 22313-1450

Sir:

Patentees respectfully request that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistakes shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY LLP

Date: Dec. 16, 2008

By: 
Gene M. Garner, II
Registration No. 34,172

1201 New York Ave, N.W., 7th Floor
Washington, D.C. 20005
Telephone: (202) 434-1500
Facsimile: (202) 434-1501

DEC 18 2008

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO : 7,444,842

DATED : November 4, 2008

INVENTOR(S) : Hyun Sook KIM et al.

Column 8, Line 11, before "key" change "an" to --a--.

Column 8, Lines 47-48, change
"a rotary tub provided in the water tub; and
a detergent feed unit;"
to
--a rotary tub provided in the water tub;
a detergent feed unit; and--.

MAILING ADDRESS OF SENDER:
STAAS & HALSEY LLP
1201 New York Ave., N.W.
7th Floor
Washington, DC 20005

PATENT NO. 7,444,842

No. of add'l copies
@ 50¢ per page

⇒

DEC 18 2008